

**Before Pilot Project at Leratong Hospital**

**During Pilot Project at Leratong Hospital**



Sharps containers with large hole for direct vertical loading



Sharps container with horizontal loading via safety sluce



Broken pedal bin for HCRW in sluice room



Wall mounted bin with liner in sluice room

***Before Pilot Project at Leratong Hospital***



Nurse trolley with red bag hanging loose fixed with tape

***During Pilot Project at Leratong Hospital***



Nurse trolley with puncture proof holder for red bag



Large standing bin for domestic waste in corridors etc.



Wall mounted rack with bag for domestic waste

**Before Pilot Project at Leratong Hospital**



140 litre Cardboard box receiving HCRW in the wards

**During Pilot Project at Leratong Hospital**



100 litre puncture proof stackable box for HCW in sluice



Filled 140 litre cardboard box sealed and awaiting collection




Filled thick red liner being removed from stand in sluice

**Before Pilot Project at Leratong Hospital**



Filled sealed HCRW cardboard box awaiting collection in corridor

**During Pilot Project at Leratong Hospital**



No HCRW is left unattended in public places!



Internal collection of cardboard boxes with HCRW



Internal collection of reusable stackable boxes in cage trolley

**Before Pilot Project at Leratong Hospital**



Internal collection of cardboard boxes with HCRW

**During Pilot Project at Leratong Hospital**



Internal collection of thick liners using 770 litre wheelie bin



Manual transfer of non-puncture proof cardboard boxes to truck



Wheeled transfer of stackable boxes using lifting tail gate

***Before Pilot Project at Leratong Hospital***



Manual feeding of non-puncture proof cardboard boxes to incinerator

***During Pilot Project at Leratong Hospital***



Mechanical lifting of wheelie bins into hopper of incinerator



Washing and disinfection of 770 litre wheelie bin



Drying of 770 litre wheelie bin after cleaning